

Yealink VCS Series Endpoint Release Notes of Version 52

Content

Yea	alink VCS Series Endpoint Release Notes of Version 525	1
Yea	alink VCS Series Endpoint Release Notes of Version 52	2
1.	Introduction	2
2.	Feature List	2
3.	Optimization	3
4.	Bug Fixes	4
5.	Notes for Upgrading Version	4



Yealink VCS Series Endpoint Release Notes of Version 52

1. Introduction

Firmware Version of the VCS Series Endpoint:			
MeetingEye400	Standard: 120.351.0.15 upgraded to 120.352.0.35		
	Yealink VC Cloud: 120.351.1000.15 upgraded to 120.352.1000.35		
MeetingEye600	Standard: 120.351.0.15 upgraded to 120.352.0.35		
	Yealink VC Cloud: 120.351.1000.15 upgraded to 120.352.1000.35		
VC200-E	Standard: 118.351.0.1 upgraded to 118.352.0.30		
	Yealink VC Cloud: 118. 351.1000.10 upgraded to 118.352.1000.30		
VP59	91.343.0.20 upgraded to 91.352.0.15		
Accessory Version of the VCS Series Endpoint:			
CTP18	Standard: 137.352.0.10		
	Yealink VC Cloud: CTP18: 137.352.1000.10		
CTP20	Standard: 85.352.0.10		
	Yealink VC Cloud: 85.352.1000.10		
WPP20	81.352.0.30		

Release Date: December 13th, 2021.

2. Feature List

- MeetingEye400/MeetingEye600/VC200-E/VP59 supported working with Yealink Meeting Server (YMS) or Yealink Meeting (YM) of version 40
 - 1) Supported signing in to the account of YMS/YM.
 - 2) Supported enterprise security configuration, enterprise security management, conference control, and participants' rights in conferences on the server.
 - 3) Supported the voice-activated feature on the server, which can highlight the speaker or display the current speaker's video according to the layout effect in real-time.
 - 4) Supported the server controls endpoint and custom conference layout



display

- Added camera preset to the VC200-E, and you can operate the camera preset through the remote control.
- Added the feature of BYOD mode for MeetingEye400/MeetingEye600/VC200-E.
 After connecting the VC200-E to the VCH51, you can use a USB-C cable to connect the VCH51 and computer then select the VC200-E as the audio and video device on the computer for a better conference experience.
- Added the feature of switching content sharing devices for MeetingEye400/MeetingEye600/VC200-E.
- Added the feature of Phone and Meeting for VCS series endpoint in the idle screen,
 which can quickly create or join a conference through the Meeting.



3. Optimization

- Optimized the meeting control experience when using CT18/CTP20 to control cloud meetings.
 - 1) Optimized the conference control features, such as Chat room, waiting room, conference control experience for moderator, etc.
 - 2) Optimized the feature of split layout and pin video, and you can pin video or unpin video of any participant.
 - 3) Optimized the interactive user interface and detailed display effect, and you can click the conferencing title to view conferencing information quickly.
 - 4) Supported quick switching of multiple content sharing.
- Optimized the interactive user interface for WPP20.
 - 1) Optimized the theme style and the entrance of presentation connection, and



supported quick configuration of sharing content mode.



- 2) Optimized the issue that the icons often affect the operation when sharing content via WPP20.
- 3) Optimized the issue that the software cannot pop up the reminder normally.
- 4) Changed the fixed toolbar of the whiteboard to a floating toolbar to improve usability.
- Optimized the upgrade feature and supported removing imported firmware from the web user interface.
- Optimized the icon of Meeting and Phone for VC200-E/VP59 in the idle screen.

4. Bug Fixes


- Fixed known stability issues related to camera control.
- Fixed an issue in the scene of high network concurrency.
- Fixed the stability and compatibility issues of WPP20 auxiliary stream.
- Fixed some supportive issues related to YMS deployment.

5. Notes for Upgrading Version

 When registering the YMS-2X server with the firmware version 52, you need to disable the "HTTP access service" option on the web user interface (Account-> VC Platform).



Video Conference Platform



 The firmware version of the VCS system and the accessories must be matched before you can use them usually.